

FIRE PREVENTION

3 Fur Marskel

P 0 BOX 80245 SEATTLE, WA 98108

PHONE (206) 296 7392 OR 206 205 097A

	_	•	' <
Date <u>07-14-99</u>	 		

ADDRESS 7585 Perimeter Road S., Seattle, WA 98108

NAME OF BUILDING

Ameriflight/UPS Hangar (Hangar #5)

NOTICE OF VIOLATION-WARNING:

Violation of Uniform Fire Code (1994):

Article 24- Airports, Heliports and Helistops Section 2401 -- General: 2401.8 Sources of Ignition. ... sources of ignition shall not be permitted in an aircraft hangar, except in approved location. Article 79--Flammable and Combustible Liquids --Section 7901 -- General EPORT OF INSPECTION: 7901.10 Sources of Ignition. In locations REPORT OF INSPECTION:

where flammable vapors could be present, precautions shall be taken to prevent ignition by eliminating or controlling sources of ignition.

On 07-09-99, at 2230 hours, a fire alarm was reported to King County Airport Police/Aircraft Rescue and Fire Department, for 7585 Perimeter Rd S., by Security Link. Seattle Fire Department was also notified. The Airport Fire Department and Seattle Fire Department both responded with fire vehicles. This fire alarm was caused by the smoke from a barbecue which Ameriflight employees were having INSIDE the hangar. There was no fire. The alarm could not be reset until 0001 on 07-10-99.

THE USE OF A BARBECUE INSIDE AN AIRCRAFT HANGAR IS A FIRE HAZARD AND IS A VIOLATION OF THE ABOVE LISTED SECTIONS OF THE UNIFORM FIRE CODE.

USE OF BARBECUES ON KING COUNTY AIRPORT MUST BE OUTSIDE, AT LEAST 10 FT FROM

ANY BUILDING OR COMBUSTIBLES AND 50 FT FROM ANY AIRCRAFT.

CORRECTIVE ACTION:

Inform all employees and take whatever other actions are necessary to prevent such incidents in the future. If you have any questions on fire safety contact Cpl Dickie at 206 296 7392.

On 07-12-99, at 0930, Cpl Dickie contacted Marv Besch, Chief Pilot at Ameriflight, and informed him of the above incident. Mr. Besch was informed that barbecues were prohibited inside hangars. Mr. Besch located the employees Inspector's Name: Manuale and told them of the correct procedure. GRADEAL S. H. DICKLE

Signature of person representing property owner

DELIVERED ON 7-15-99 TO AMERIFLIGHT FOR ROD FICHTEES SIGNATURE AND RETURN.

KCSlip4 34162